

FOR FURTHER INFORMATION PLEASE CONTACT:

HESTRA-HANDSKEN AB  
P.O. BOX 116  
SE-330 27 HESTRA  
SWEDEN

TEL. + 46 370 33 97 00  
FAX. + 46 370 33 97 05

DISTRIBUTED BY:


NORDBO KÖLDSKYDD AB  
P.O. BOX 14  
SE-457 02 GREBBESTAD  
SWEDEN

TEL. + 46 (0) 525 644 60  
FAX. + 46 (0) 525 644 69


# Nordbo

WORK GLOVE  
ART. NO. 8482

EN 388



EN 511



CE

## HESTRA®

GLOVES - GANTS - HANDSCHUHE - HANDSKAR

## HESTRA®

GLOVES - GANTS - HANDSCHUHE - HANDSKAR

## USER INSTRUCTIONS

### HESTRA NORDBO work glove art. No 8482

**GLOVE DESCRIPTION** - 5-Finger glove, pre curved design, knitted cuff, wrist elastic in palm and back.

Fabric: 100% polyamide  
Palm material: Goat leather  
Insulation: 100gr. fibrefill + 10 mm foam on backhand.  
Knit cuff: 100% acrylic

These gloves are classed as Personal Protective Equipment (PPE) by the European PPE Directive 89/686/EEC and have shown to comply with this Directive through the Harmonised European Standard EN 388:1994, EN 511:1994 and EN 420:1994

Certification body: Centexbel, Technopark 7,  
90052 Swijnaarde, Belgium  
(Notified body 0493).

**Carefully read these instructions before using these gloves.**

These gloves are designed to minimise the risk/provide protection against mechanical risks and cold during work in cold environment for example in cold storage.

However, always remember that no item of PPE can provide full protection and care must always be taken while carrying out the risk-related activity.

**PERFORMANCE AND LIMITATIONS TO USE** - These gloves have been tested in accordance with EN 388:1994 and EN 511:1994 and have achieved the following performance levels:

#### EN 388:1994

Abrasion resistance	level 1
Blade cut resistance	level 2
Tear resistance	level 2
Puncture resistance	level 3

#### EN 511:1994

Convective cold	level 2
Contact cold	level 2

Never wear the gloves in temperatures exceeding 50 centigrades.

**FITTING AND SIZING** - Only wear gloves of suitable size. Gloves which are too loose or too tight will restrict the movement and will not provide the optimum level of protection. The size of the gloves are marked on a label at the hand back. Following sizes are available: 8, 9, 10, 11 (sizes are defined in accordance with EN 420:1994)

**CLEANING/MAINTENANCE/STORAGE** - Preferably clean the gloves using a brush. Washing in water or dry cleaning can change the characteristics of the material, in which case the manufacturer do not accept any liability.

Both new and used gloves should be thoroughly inspected before use. If the gloves become damaged, it will NOT provide the optimum level of protection, and therefore should be immediately replaced.

Gloves should be ideally stored in dry condition in original package.

**MARKING** - The gloves are marked with:

HESTRA, NORDBO 8482, size, CE-mark and pictogram for standards EN 388:1994 and EN 511:1994